AUTOCAR

Autocar GmbH
Hauptstraße 98, 40210 Düsseldorf, Germany
+49 (0)211 1234567
service@autocar-gmbh.de
www.autocar-gmbh.de

Inspection powered by ANYLINE

Customer:	**John Doe**	Vehicle:	**Audi - Q4 e-tron (12992km)**
Identifier:	**125363789**	License Plate:	**ANYL1NE**
Inspection Date:	**03.04.25** at **09:09**	VIN:	**5GZCZ43D13S812719**

TIRE ON RECALL
Front tires on recall in the U.S.
Check if your tire is affected in your region.

TIRE SEASON
Switch to appropriate tires for the current season.

1300 KM
Potential remaining distance



These figures are illustrative only and do not guarantee actual stopping performance.

Left Front Tire

Replace Now (Tread ≤ 3.0mm)

3.1mm 1.6mm 3.1mm

Notes
- There is severe shoulder wear.
- Tire tread is less than recommended minimum.
- Use extreme caution in all conditions.

Right Front Tire

Replace Now (Tread ≤ 3.0mm)

3.1mm 1.6mm 3.1mm

Notes
- There is severe outside wear.
- Tire tread is less than recommended minimum.
- Use extreme caution in all conditions.



Left Rear Tire

Good Condition (Tread ≥ 4.0mm)

5.1mm 6.2mm 5.1mm

Notes
-

Right Rear Tire

Good Condition (Tread ≥ 4.0mm)

5.1mm 6.2mm 5.1mm

Notes
-

Left Front Tire
Replace Now
Tread ≤ 3.0mm

Bridgestone - Turanza T 005
205/55R16
DOT 7G8K U2W 4819 (Age: 6y/o)

Notes
⚠ This tire has been recalled.
Severe shoulder wear. Advanced tire age.

Right Front Tire
Replace Now
Tread ≤ 3.0mm

Bridgestone - Turanza T 005
205/55R16
DOT 7G8K U2W 4819 (Age: 6y/o)

Notes
⚠ This tire has been recalled.
Advanced tire age. Presence of cracks in the rubber.

Left Rear Tire
Good Condition
Tread ≥ 4.0mm

Bridgestone - Turanza T 005
205/55R16
DOT 7G8K U2W 4821 (Age: 3y/o)

Notes
-

Right Rear Tire
Good Condition
Tread ≥ 4.0mm

Bridgestone - Turanza T 005
205/55R16
DOT 7G8K U2W 4821 (Age: 3y/o)

Notes
-

Summary

Customer suspects rear tire losing air overnight

At least one tire has low tread remaining. Increased risk of reduced traction, longer breaking distances, and potential aquaplaning, especially in wet conditions. Consider replacing the tire very soon.

At least one tire is six years old or older, which increases the risk of damage or blowouts. Consider replacing tire soon.

Inspection ID:
ea6717a3ab57-4c2b-993x3-071cfcc17d88
Employee ID: 4520694

Disclaimer: This report is solely intended as a reference. Anyline accepts no liability for decisions made based on this data.

Good Condition (Tread ≥ 4.0mm) | **Replace Soon** (3.0mm ≤ Tread ≤ 4.0mm) | **Replace Now** (Tread ≤ 3.0mm)