TireBuddy


Customer: **Anyline**
Identifier: **CASE-2026-0001**
Date: **14.10.2026 | 12:21**

Vehicle: **BMW 3 Series Sedan (G20) M Sport | 2023 | 48,250 km**
License Plate: **ANY L1NE**
VIN: **WVWZZZ1KZDW**13*3**

Tire Age Status
All tires are under 5 years old.

42,000 - 35,000 km
Estimated remaining tire life

Matching Tires
All four tires have the same size and model.



*These figures are illustrative only and do not guarantee actual braking performance.
Scenario: Speed 80 km/h - Wet road

Left Front Tire

Good Condition (Tread ≥ 4.0mm)

7.0mm 6.3mm 6.5mm

Notes

Right Front Tire

Good Condition (Tread ≥ 4.0mm)

7.4mm 6.5mm 7.5mm

Notes



Left Rear Tire

Good Condition (Tread ≥ 4.0mm)

6.7mm 7.0mm 6.7mm

Notes

Right Rear Tire

Good Condition (Tread ≥ 4.0mm)

6.8mm 6.8mm 6.6mm

Notes

Good Condition (Tread ≥ 4.0mm) | **Replace Soon** (3.0mm ≤ Tread ≤ 4.0mm) | **Replace Now** (Tread ≤ 3.0mm)

Left Front Tire
Continental WinterContact TS 860 S | Winter · 3PMSF · M+S
DOT 2025/09 (Age: 1y/o) | 205/60R16 96H | Extra load



Right Front Tire
Continental WinterContact TS 860 S | Winter · 3PMSF · M+S
DOT 2025/09 (Age: 1y/o) | 205/60R16 96H | Extra load



Left Rear Tire
Continental WinterContact TS 860 S | Winter · 3PMSF · M+S
DOT 2025/09 (Age: 1y/o) | 205/60R16 96H | Extra load



Right Rear Tire
Continental WinterContact TS 860 S | Winter · 3PMSF · M+S
DOT 2025/09 (Age: 1y/o) | 205/60R16 96H | Extra load



Summary

Seasonal tire check before winter.
All four tires have good tread depth and match in size and model. No action needed before the next seasonal check.

Inspection ID: **demo-2026-1014-1221-anyline**

Employee ID: **DEMO**

Disclaimer: This is a sample report with demo data. Test License Plate, VIN partially hidden for privacy.
This report is solely intended as a reference. Anyline accepts no liability for decisions made based on this data.

Inspection powered by ANYLINE